

GOOD CONSTRUCTION

PREVENT SCREEN FROM

FALLING OR BLOWING OFF
YOUR INCINERATOR.

GOOD HEAVY METAL
BARREL

NO HOLES IN SIDES OR
BOTTOM OF BARREL.

HELP COMBUSTION &
CLEAN BURNING

PUNCH HOLES AND SHOVE STEEL
RODS OR PIPES THROUGH BARREL.
THIS WILL HOLD BURNING MATERIAL
UP AND GIVE A CLEAN FAST BURN.

HEAVY SCREEN

AT LEAST 14 GAUGE
WITH 1/4 INCH HOLES.

